



Condition Report

Sale 2004 - 10/08/2020 10:00 - Live Three Day Webcast Medical Sale from Monday 10th August to Wednesday 12th August *** Day**

Sale Date 10-08-2020 10:00

Location: Malmesbury, Wiltshire, UK.

Viewing: Please note – Due to COVID-19 viewing and attending the live auction is by appointment only until further notice. If you would like more information on an item

Removal: All items to be collected by Wednesday 19th August at 4pm. Items not collected by this date will incur late collection charges.

These reports are compiled by our Medical Engineering Team and are for guidance only - all lots are sold as seen, as per our Conditions of Sale. We recommend that wherever possible you inspect lots prior to purchase.

Lot 1 Smith & Nephew Stack System with Sony Monitor, Dyonics Power 2 Control

Condition Report: Stack system powered up successfully with all items in working order. Sony monitor produced a good image with its control arm in full working order. Monitor other than some light scratch marks is in a good physical condition. Dyonics power II control system was tested with a power mini shaver (not included with lot) and foot switches, all functions were operational and foot switch was in full working order. 660 HD Image management system was fully operational, touch screen was in working order and patient data and images/videos could be saved and reviewed. HD camera system and associated HD1200 camera head were both fully functional. White balance was carried out successfully. The 500XL Xenon light source produced light successfully with brightness fully adjustable. Overall this stack system is in good physical condition, with some signs of wear on the foot switches only. Trolley, castors and breaks are in good working order.

Lot 2 Smith & Nephew Stack System with Sony Monitor, Dyonics Power 2 Control

Condition Report: Stack system powered up successfully with all items in working order. Sony monitor produced a good image with its control arm in full working order. Monitor is in a good physical condition. Dyonics power II control system was tested with a power mini shaver (not included with lot), all functions were operational. 660 HD Image management system was fully operational, touch screen was in working order and patient data and images/videos could be saved and reviewed. HD camera system and associated HD1200 camera head were both fully functional. White balance was carried out successfully. The 500XL Xenon light source produced light successfully with brightness fully adjustable. Overall this stack system is in good physical condition. Trolley, castors and breaks are in good working order.

Lot 3 Meridian Merilite YAG Laser with Foot Switch

Serial No: 10.0450.17



Manufactured: 07 1995

Accessories: Footswitch

Condition Report: Unit power up with the displays and key pad working. Continuous bleeping and "Not Ready" is displayed. The unit is with key but a spare one was used to test the system. However, with fibre it was not possible to fully test the laser unit. Unit is in good physical condition.

Lot 4 Respironics Bipap Vision Ventilator

Condition Report: Unit powered up with LCD and key pad in good working order. The unit completed its self start tests. Function menus are accessible and parameter and alarm settings are functional. The air turbine is working fine. Basic tests were carried out on the system. Modes: CPAP was operational however S/T did not function as expected. Backup battery is not working and system is in good physical condition.
SN: 127795

Lot 5 Respironics Bipap Focus Ventilator

Condition Report: Unit powered up with LCD and key pad in good working order (some keys have some cosmetic damage). The unit completed its self start tests. Function menus are accessible and parameter and alarm settings are functional. The air turbine is working fine. Basic tests were carried out on the system. Mode: S/T & CPAP were both operational. Backup battery is not working and system is in fair physical condition with regions of wear.
Operating hrs: 7120
SN: 107902

Lot 6 Olympus Stack System with Olympus OEV191H Monitor, Olympus Exera II CV

Condition Report: All items on the stack system powered up. The CV-180 video processor did not detect the camera when attached, the unit came with an Olympus note indicating the unit has main board failure. The light source, keyboard and monitor were all working as expected. All items are in fair physical condition with signs of wear.

Lot 10 Deka Smartlipo Laser 3 Phase with Key, Foot Switch and Interlock Plug | SN

Serial No: NH6A205L

Accessories: Key
Footswitch
Interlock plug

Condition Report: Unit power up and LCD working. System fault is displayed. Fibre is not included, unable to carry out test. Unit is in fair physical condition with the plastic rim at the base partly broken.

Lot 11 Topcon 3D OCT 2000 Optical Coherence Tomography Unit | DOM 2009 | SN

Condition Report: The OCT unit powers up, the LCD screen and joystick control are working accordingly but the system does not display any information. The outer cover is loose and the base



unit is missing two small plastic covers. The entire chin rest assembly is missing. Otherwise the unit is in satisfactory physical condition. The unit does not come with a table or the workstation / computer system.

Lot 12 Topcon 3D OCT 2000 Optical Coherence Tomography Unit | DOM 2010 | SN

Condition Report: The OCT unit powers up, the LCD screen, joystick control and motorised chin rest adjustment are working accordingly. However, the system fails to complete the startup process and continuously attempts to reboot. Otherwise the unit is in satisfactory physical condition with some damage to the side cover of the OCT unit. The unit does not come with a table or the workstation / computer system.

Lot 13 Topcon 3D OCT 2000 Optical Coherence Tomography Unit | DOM 2012 | SN

Serial No: 683036

Manufactured: 2012

Condition Report: The OCT unit powers up, the Topcon logo briefly appears on the the LCD screen but the system does not display any further information. The joystick control and motorised chin rest adjustment are working accordingly. Overall the unit is in satisfactory physical condition. The unit does not come with a table or the workstation / computer system.

Lot 14 Topcon 3D OCT 2000 Optical Coherence Tomography Unit | DOM 2012 | SN

Condition Report: The OCT unit powers up and completes the initial startup process but displays 'SDL light source error' in the main menu. The LCD screen and joystick are working accordingly. The base unit is missing two small plastic covers. The adjustable part of the chin rest assembly is missing. Otherwise the unit is in satisfactory physical condition. The unit does not come with a table or the workstation / computer system.

Lot 15 Maquet Alphamaxx Operating Table | DOM 2005 | SN 00125 | with Remote

Condition Report: The Alphamaxx operating table powered up with corded hand control and emergency key pad in good working order. Battery was not functional the unit was tested on mains power. Head rest mechanical adjustment is functional. All the motorised positioning, such as Trendelenburg/reverse Trend, Flex, Reflex, Left & Right Tilt, Leg and back adjustments and up/down lift are working fine. The zero levelling is working as well. The cushions set is in fair condition with one missing. Motorised lock and casters are fully functional. Unit is in fair physical condition with scratches consistent to use.

Lot 16 Alcon Accurus 200PS Ophthalmic Surgical System with Remote Control and Foot



Serial No: 0702749101X

Manufactured: 09 2007

Accessories: Remote Control

Foot Switch

Software: Version 4.54

Condition Report: The Accurus surgical system powers up and completes the initialisation process successfully. Display panel with touch screen feature is in good working order and all system menus are accessible within the anterior mode. Footswitch and remote control are also functional. The motorised IV pole height adjustment is not working. No handpieces or accessories included with the unit and therefore the system could not be fully tested. Air hose is included. The instrument tray is intact and overall the unit is in reasonable physical condition.

Lot 17 Alcon Accurus 200PS Ophthalmic Surgical System with Remote Control, User

Serial No: 0501357201X

Manufactured: 03 2005

Accessories: Foot Switch

Remote Control

User Manual

Software: Version 4.52

Condition Report: The Accurus surgical system powers up and completes the initialisation process successfully. Display panel with touch screen feature is in good working order and all system menus are accessible within the anterior mode. Footswitch and remote control are also functional. The motorised IV pole height adjustment is not working. No handpieces or accessories included with the unit and therefore the system could not be fully tested. Air hose is included. The instrument tray is intact and overall the unit is in reasonable physical condition.

Lot 18 Arthrex Synergy HD3 Stack System with Arthrex Synergy HD3 Image

Associated Equipment: Sony UP-DR80MD Printer

Accessories: Arthrex Synergy HD3 Image Management System
Serial Number BAF0044

2 x Arthrex AR-3210-0001 Synergy HD3 Camera Heads
Serial Number AA4821, AA3528



2 x Arthrex AR -3360-4030 Arthroscope, 30degree HD Rigid Scopes
Serial Numbers 930080, 927333

2 x Arthrex AR3371-4001 Sheath System, High Flow, Fenestration

2 x Fibre Optic Light Guide Cable

Condition Report: The stack trolley and all associated units power up accordingly. The LCD monitor, video processor/ light source, both camera heads, rigid scopes and fibre optic cbles are in good working order. The system produces clear images and the white balance setting, camera head buttons and focus controls are all in good working order. The Galaxy tablet is also functional, the application software is fully accessible with patient registration, image capturing and video recording modes all working accordingly. The printer is also in good working order. Overall the stack system is in good physical condition with minor signs of wear.

Lot 19 Arthrex Synergy HD3 Stack System with Arthrex Synergy HD3 Image

Associated Equipment: Sony UP-DR80MD Printer

Accessories: Arthrex Synergy HD3 Image Management System
Serial Number LAC0080

2 x Arthrex AR-3210-0001 Synergy HD3 Camera Heads
Serial Number AA3689, AA3032

2 x Arthrex AR -3360-4030 Arthroscope, 30degree HD Rigid Scopes
Serial Numbers 927589, 927245

2 x Arthrex AR3371-4001 Sheath System, High Flow, Fenestration

2 x Fibre Optic Light Guide Cable

Condition Report: The stack trolley and all associated units power up accordingly. The LCD monitor, video processor/ light source, both camera heads, rigid scopes and fibre optic cbles are in good working order. The system produces clear images and the white balance setting, camera head buttons and focus controls are all in good working order. The Galaxy tablet is also functional, the application software is fully accessible with patient registration, image capturing and video recording modes all working accordingly. The printer is also in good working order. Overall the stack system is in good physical condition with minor signs of wear.

Lot 20 Arthrex Synergy HD3 Stack System with Arthrex Synergy HD3 Image

Associated Equipment: Sony UP-DR80MD Printer



Accessories: Arthrex Synergy HD3 Image Management System
Serial Number LAC0138

2 x Arthrex AR-3210-0001 Synergy HD3 Camera Heads
Serial Number AA6226, AA3518

2 x Arthrex AR -3360-4030 Arthroscope, 30degree HD Rigid Scopes
Serial Numbers 1220419, 927570

2 x Arthrex AR3371-4001 Sheath System, High Flow, Fenestration

2 x Fibre Optic Light Guide Cable

Condition Report: The stack trolley and all associated units power up accordingly. The LCD monitor, video processor/ light source, both camera heads, rigid scopes and fibre optic cables are in good working order. The system produces clear images and the white balance setting, camera head buttons and focus controls are all in good working order. The Galaxy tablet is also functional, the application software is fully accessible with patient registration, image capturing and video recording modes all working accordingly. The printer is also in good working order. Overall the stack system is in good physical condition with minor signs of wear.

Lot 21 Olympus GIF-XQ230 Video Gastroscope | SN 2603232

Condition Report:

- **Insertion Tube** – Good condition
- **Bending mechanism & Angulation Control** – Good movements & locks
- **Light Guide Cable & Light Transmission** – Good
- **Objective Lens & Focussing** – Good optics
- **Remote Control Switches** – Fully functional
- **Distal End** – Good condition
- **Image Quality** – Good image
- **Instrument Channel (s)** – Clear
- **Leak Test** – Pass
- **Overall Condition** – Good overall condition
- **Dimension:** 10 x 1000 mm

Lot 22 Olympus CYF-4 Fiber Cystoscope | SN W304949

Condition Report:

- **Insertion Tube** – Good condition
- **Bending mechanism & Angulation Control** – Good movements and lock
- **Light Guide Cable & Light Transmission** – Good
- **Objective Lens & Focussing** – Good optics with 2 damaged fibres
- **Remote Control Switches** – N/A
- **Distal End** – Good condition
- **Image Quality** – Good image quality



- **Instrument Channel (s)** – Clear
- **Leak Test** – Pass
- **Overall Condition** – Good optics & physical condition.
- **Dimension:** 5.7 x 370 mm

Lot 23 Olympus GIF-XQ230 Video Gastroscope | SN 2825877

- Condition Report:
- **Insertion Tube** – Fair condition, rubber housing on angulation region damaged.
 - **Bending mechanism & Angulation Control** – Good movements & locks
 - **Light Guide Cable & Light Transmission** – Good light transmission, guide cable is discoloured.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Failed
 - **Overall Condition** – Poor overall condition, regions of damage and wear and failed leak test.
 - **Dimension:** 10 x 1000 mm

Lot 24 Olympus GIF-XQ240 Video Gastroscope | SN 2336650 | DOM 2003

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Fair movements & locks
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition
 - **Dimension:** 10.3 x 1000 mm

Lot 25 Olympus GIF-XQ230 Video Gastroscope | SN 2825900

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition



- **Dimension:** 10.3 x 1000 mm
-

Lot 26 Olympus GIF-XQ260 Video Gastroscope | SN 2421685 | EST DOM 2014

- Condition Report:
- **Insertion Tube** – Good condition other than one bite mark.
 - **Bending mechanism & Angulation Control** – Poor movements - U/D direction faulty.
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Reasonable overall condition
 - **Dimension:** 10.3 x 1000 mm
-

Lot 27 Olympus GIF-XQ240 Video Gastroscope | SN 2812331

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements & lock
 - **Light Guide Cable & Light Transmission** – Good other than discolouration.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Fair image, cloudy.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition other than cloudy image.
 - **Dimension:** 10.4 x 1000 mm
-

Lot 28 Olympus PCF Type P240 Video Colonoscope | SN 2300090 | DOM 2003

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Reasonable condition with signs of wear
 - **Image Quality** – Reasonable image
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Fair overall condition
 - **Dimension:** 12 x 1600 mm
-

Lot 29 Olympus CYF-4 Fiber Cystoscope | SN W304950

- Condition Report:
- **Insertion Tube** – Good condition



- **Bending mechanism & Angulation Control** – Good movements and lock
- **Light Guide Cable & Light Transmission** – Good
- **Objective Lens & Focussing** – Good optics with no damaged fibres
- **Remote Control Switches** – N/A
- **Distal End** – Good condition
- **Image Quality** – Good image quality
- **Instrument Channel (s)** – Clear
- **Leak Test** – Pass
- **Overall Condition** – Good optics & physical condition.
- **Dimension:** 5 x 370 mm

Lot 30 Olympus CF-IT200L Video Colonoscope (Damaged) | SN 2910363

- Condition Report:
- **Insertion Tube** – Discoloured & rubber coating on angulation mechanism detached.
 - **Bending mechanism & Angulation Control** – Good movements.
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Failed
 - **Overall Condition** – Fair overall condition, with leak and damaged angulation casing.
 - **Dimension:** 15 x 1600 mm

Lot 31 Olympus PCF Type P240 AL Video Colonoscope | SN 2400155 | DOM 2004

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition
 - **Dimension:** 11 x 1600 mm

Lot 32 Olympus GIF-XQ240 Video Gastroscope | SN 2812322

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements & lock
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional



- **Distal End** – Good condition
- **Image Quality** – Good image
- **Instrument Channel (s)** – Clear
- **Leak Test** – Pass
- **Overall Condition** – Good overall condition
- **Dimension:** 10 x 1000 mm

Lot 33 Olympus CYF-5 Fiber Cystoscope | SN W804558

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – No cable included, tested with spare.
 - **Objective Lens & Focussing** – Good optics with one damaged fibre.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good optics & physical condition.
 - **Dimension:** 5.5 x 370 mm

Lot 34 Olympus CYF-4 Fiber Cystoscope | SN W304947

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – Good condition, good transmission.
 - **Objective Lens & Focussing** – Good optics with one damaged fibre.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good optics & physical condition.
 - **Dimension:** 5.5 x 370 mm

Lot 35 Olympus CYF-5 Fiber Cystoscope | SN W804556

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – No cable included, tested with spare.
 - **Objective Lens & Focussing** – Good optics other than 5-6 damaged fibres in one small cluster.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass



- **Overall Condition** – Good optics & physical condition.
- **Dimension:** 5.5 x 370 mm

Lot 36 Olympus CF-IT200L Video Colonoscope | SN W2400185

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition
 - **Dimension:** 14.7 x 1600 mm

Lot 37 Olympus CYF-4 Fiber Cystoscope | SN W405269

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – Good condition
 - **Objective Lens & Focussing** – Good optics other than 5 damaged fibres.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good optics & physical condition, other than few damaged fibres.
 - **Dimension:** 6 x 370 mm

Lot 38 Olympus CYF-4 Fiber Cystoscope | SN W304948

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – Good condition
 - **Objective Lens & Focussing** – Good optics & focussing with no damaged fibres.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good optics & physical condition.
 - **Dimension:** 5.5 x 370 mm

Lot 39 Olympus GIF-XP260N Video Gastroscope | SN 2804599 | DOM 2008



- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Fair movements & locks
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Fair optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition
 - **Dimension:** 6.1 x 1000 mm

No carry case

Lot 40 Olympus GIF-XP260N Video Gastroscope | SN 2701805 | DOM 2007

- Condition Report:
- **Insertion Tube** – one dent on the insertion tube
 - **Bending mechanism & Angulation Control** – Fair movements & locks
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Fair optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition
 - **Dimension:** 6.0 x 1000 mm

No carry case

Lot 41 Olympus PCF2405 Video Sigmoidoscope | SN 2400171 | DOM 2004

- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Good movements & locks
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good
 - **Image Quality** – Very good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition
 - **Dimension:** 11.9 x 900 mm

Lot 42 Olympus CF-Q260DL Video Colonoscope | SN 2911122 | DOM 2009



- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Good movements & locks
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Not working properly
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition, except for the controls
 - **Dimension:** 13.7 x 1600 mm
-

Lot 43 Olympus CF-Q260DL Video Colonoscope | SN 2610371 | DOM 2016

- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Good movements and locking mechanism functional.
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition, with small signs of wear in the control body.
 - **Dimension:** 12.4 x 1600 mm
-

Lot 44 Olympus GIF-XQ260 Video Gastroscope | SN 2310860 | DOM 2013

- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Fair movements. Locking mechanism is functional.
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good focussing.
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition.
 - **Image Quality** – Fair image quality, .
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition, with some small wear on control body.
 - **Dimension:** 10 x 1000 mm
-

Lot 45 Olympus GIF-Q260 Video Gastroscope | SN 2958032 | DOM 2009

- Condition Report:
- **Insertion Tube** – Good , one small kink at control body end.
 - **Bending mechanism & Angulation Control** – Fair movements. Locking



mechanism is functional.

- **Light Guide Cable & Light Transmission** – Good
- **Objective Lens & Focussing** – Good focussing.
- **Remote Control Switches** – Fully functional
- **Distal End** – Good condition.
- **Image Quality** – Good image quality.
- **Instrument Channel (s)** – Clear
- **Leak Test** – Pass
- **Overall Condition** – Good overall condition with small signs of wear on control body and small kink on the end of insertion tube.
- **Dimension:** 10.2 x 1000 mm

Lot 46 Olympus GIF XQ260 Video Gastroscope | SN 2034982 | DOM 2010

- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Fair movements, limited movement in downwards direction. Locking mechanism is functional.
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition, with small signs of wear in the control body.
 - **Dimension:** 10 x 1000 mm

Lot 47 Olympus PCF-Q260AL Paediatric Video Colonoscope | SN 2310688 | DOM 2013

- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Good movements and locking mechanism functional.
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition, with small signs of wear in the control body.
 - **Dimension:** 12.4 x 1600 mm

Lot 48 Olympus CF-Q260DL Video Colonoscope | SN 2911365 | DOM 2009

- Condition Report:
- **Insertion Tube** – Good condition



- **Bending mechanism & Angulation Control** – Good movements and locks
- **Light Guide Cable & Light Transmission** – Good
- **Objective Lens & Focussing** – Good optics
- **Remote Control Switches** – Fully functional
- **Distal End** – Good condition
- **Image Quality** – Good image quality
- **Instrument Channel (s)** – Clear
- **Leak Test** – Pass
- **Overall Condition** – Good overall condition, minor scratches on the control handle
- **Dimension:** 14.0 x 1600 mm

Lot 49 Olympus CF-Q260DL Video Colonoscope | SN 2311737 | DOM 2013

- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Good movements & locks
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition
 - **Dimension:** 14.0 x 1600 mm

Lot 50 Olympus GIF-XP260 Video Gastroscope | SN 2411065 | DOM 2014

- Condition Report:
- **Insertion Tube** – Fair, De-laminated
 - **Bending mechanism & Angulation Control** – Fair, no downward movement, locks mechanism is functional.
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Fair optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good optics and image quality but with angulation issue. Universal cord with cracks in lamination
 - **Dimension:** 7.5 x 1000 mm

Lot 51 Olympus CYF Type V2 Video Cystoscope | SN 2620246

- Condition Report:
- **Insertion Tube** – Fair condition, some kinking.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good condition and good transmission.
 - **Objective Lens & Focussing** – Good optics.



- **Remote Control Switches** – 3/4 functional.
- **Distal End** – Good
- **Image Quality** – Good image quality
- **Instrument Channel (s)** – Clear
- **Leak Test** – Pass
- **Overall Condition** – Good overall condition.
- **Dimension:** 5.8 x 370 mm

Lot 52 Olympus CYF Type V2 Video Cystoscope | SN 2620243

- Condition Report:
- **Insertion Tube** – Fair condition, one small kink.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good condition and good transmission.
 - **Objective Lens & Focussing** – Good optics.
 - **Remote Control Switches** – All functional.
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 5.5 x 380 mm

Lot 53 Olympus CYF Type V2 Video Cystoscope | SN 2820256

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good condition and good transmission.
 - **Objective Lens & Focussing** – Good optics.
 - **Remote Control Switches** – All functional.
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 5.6 x 380 mm

Lot 54 Olympus CYF Type V2 Video Cystoscope | SN 2820260

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good condition and good transmission.
 - **Objective Lens & Focussing** – Good optics.
 - **Remote Control Switches** – All functional.
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass



- **Overall Condition** – Good overall condition.
- **Dimension:** 5.5 x 370 mm

Lot 55 Olympus CYF-5 Fiber Cystoscope | SN W400221

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – Spare guide cable used for testing.
 - **Objective Lens & Focussing** – Fair optics other than 5 damaged fibres. Focussing in working order.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good condition
 - **Image Quality** – Fair image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Failed, leak test connection port is detached.
 - **Overall Condition** – Poor physical condition, with a few damaged fibres, fair image and discolouration.
 - **Dimension:** 6 x 370 mm

Lot 56 Olympus CYF-5 Fiber Cystoscope | SN W400225

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – Spare guide cable used for testing, light transmission good.
 - **Objective Lens & Focussing** – Good optics with no damaged fibres. Focussing in working order.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good physical and working condition.
 - **Dimension:** 5 x 370 mm

Lot 57 Olympus CYF-4 Video Cystoscope | SN N102167

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – Good condition and light transmission
 - **Objective Lens & Focussing** – Good optics with no damaged fibres. Focussing in working order.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass



- **Overall Condition** – Good physical and working condition. Angulation control mechanism is damaged - still functional.
 - **Dimension:** 6 x 370 mm
-

Lot 58 Olympus CYF-3 Fiber Cystoscope | SN W804453

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – Good condition and light transmission
 - **Objective Lens & Focussing** – Fair optics with some dirt and damaged fibres. Focussing in working order.
 - **Remote Control Switches** – N/A
 - **Distal End** – Poor condition - rust.
 - **Image Quality** – Fair image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Failed
 - **Overall Condition** – Fair physical and working condition, due to rust, dirt and failed leak test.
 - **Dimension:** 6 x 390 mm
-

Lot 59 Olympus CF Type 240DL Colonoscope | SN 2700292

- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Poor movements downwards direction not functional.
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition other than faulty bending mechanism.
 - **Dimension:** 12.5 x 1600 mm
-

Lot 60 Olympus PCF Type 240S Sigmoidoscope | SN 2100015 | DOM 2001

- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Good movement and locks
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Fully functional
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition.



- **Dimension:** 12.5 x 900 mm
-

Lot 61 Olympus BF Type Type 20 Fiber Bronchoscope | SN 2800138

- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Good movement and fair locks
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Fair optics
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Fair image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Fair overall condition.
 - **Dimension:** 6.5 x 540 mm
-

Lot 62 Olympus LF-GP Intubation Fiberscope | SN W500103 | AN 165014

- Condition Report:
- **Insertion Tube** – Fair, one kink.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – No guide cable, tested with spare - light transmission good.
 - **Objective Lens & Focussing** – Fair optics, 10-15 damaged fibres
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Fair image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Reasonable overall condition.
 - **Dimension:** 4 x 600 mm
-

Lot 63 Fujinon EN450-T5 Video Enteroscope | DOM 2010

- Condition Report:
- **Insertion Tube** – Good
 - **Bending mechanism & Angulation Control** – Fair movement and locks
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 10 x 1900 mm
-

Lot 64 Pentax EG-2970K Video Gastroscope | SN A120473 | DOM 2005

- Condition Report:
- **Insertion Tube** – Good



- **Bending mechanism & Angulation Control** – Good movement and locks
- **Light Guide Cable & Light Transmission** – Good
- **Objective Lens & Focussing** – Good optics
- **Remote Control Switches** – Good
- **Distal End** – Good
- **Image Quality** – Good image quality
- **Instrument Channel (s)** – Clear
- **Leak Test** – Fail
- **Overall Condition** – Good condition other than failed leak test.
- **Dimension:** 10.8 x 1000 mm

Lot 65 Olympus LF-GP Intubation Fiberscope | SN 1300134

- Condition Report:
- **Insertion Tube** – Fair, some areas of wear and cracking.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – No guide cable, tested with spare - light transmission good.
 - **Objective Lens & Focussing** – Good optics, No damaged fibres. Focussing good.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Reasonable overall condition with signs of cosmetic wear.
 - **Dimension:** 4.2 x 600 mm

Lot 66 Olympus LF-P Intubation Fiberscope | SN 1300295

- Condition Report:
- **Insertion Tube** – Fair, signs of wear & bending.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Fair optics, large region of damaged fibres
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Fair image quality
 - **Instrument Channel (s)** – N/A
 - **Leak Test** – Fail (Very small leak)
 - **Overall Condition** – Poor overall condition.
 - **Dimension:** 2 x 600 mm

Lot 67 Olympus LF-1 Intubation Fiberscope | SN 2810009

- Condition Report:
- **Insertion Tube** – Fair, signs of wear & dents.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good
 - **Objective Lens & Focussing** – Poor optics, large region of damaged fibres
 - **Remote Control Switches** – N/A



- **Distal End** – Good
 - **Image Quality** – Poor image quality due to damaged fibres.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Fail
 - **Overall Condition** – Poor overall condition.
 - **Dimension:** 4.5 x 600 mm
-

Lot 68 Storz 11302 BD2 Intubation Scope

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – No light guide cable, tested with spare. Good transmission.
 - **Objective Lens & Focussing** – Good optics, no damaged fibres. Focussing functional.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 3.5 x 650 mm
-

Lot 69 Storz 11302 BD2 Intubation Scope

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – No light guide cable, tested with spare. Good transmission.
 - **Objective Lens & Focussing** – Good optics, no damaged fibres. Focussing functional.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 3.5 x 650 mm
-

Lot 70 Olympus GIF-XP290N Video Gastroscope | SN 2503337 | DOM 2015

- Condition Report:
- **Insertion tube** – **Good condition**
 - **Bending mechanism & Angulation control** – **Good movements & locks**
 - **Light guide cable & Light transmission** – **Good light channels**
 - **Objective lens and focusing** – **Good optics**
 - **Remote control switches** – **Fully functional**
 - **Distal end** – **Good condition**



- *Image Quality – Good image quality*
- *Working Channel (s) – Clear*
- *Leak Test – Passed*
- *Over all condition – Good overall condition*

With air/suction and water valves

Lot 71 Olympus GIF-XQ230 Video Gastroscope | SN 2715735

- Condition Report:
- *Insertion Tube* – Fair condition, few dents.
 - *Bending mechanism & Angulation Control* – Fair movements. Locking mechanism is functional.
 - *Light Guide Cable & Light Transmission* – Good
 - *Objective Lens & Focussing* – Good focussing.
 - *Remote Control Switches* – Fully functional
 - *Distal End* – Good condition.
 - *Image Quality* – Good image quality, .
 - *Instrument Channel (s)* – Clear
 - *Leak Test* – Pass
 - *Overall Condition* – Good overall condition.
 - *Dimension:* 10.2 x 1000 mm

Lot 72 Pentax FNL-7RP3 Fiber Naso-Pharyngo Laryngoscope

- Condition Report:
- *Insertion Tube* – Fair condition, one dent.
 - *Bending mechanism & Angulation Control* – Good movement.
 - *Light Guide Cable & Light Transmission* – Good guide cable. Good transmission.
 - *Objective Lens & Focussing* – Good optics, one damaged fibres. Focussing functional.
 - *Remote Control Switches* – N/A
 - *Distal End* – Good
 - *Image Quality* – Good image quality
 - *Instrument Channel (s)* – N/A
 - *Leak Test* – Pass
 - *Overall Condition* – Good overall condition, small signs of wear consistent with use.
 - *Dimension:* 2.7 x 300 mm

Lot 73 Pentax FNL-10RP3 Fiber Naso-Pharyngo Laryngoscope | SN G116684

- Condition Report:
- *Insertion Tube* – Fair condition, one dent.
 - *Bending mechanism & Angulation Control* – Good movement.
 - *Light Guide Cable & Light Transmission* – Good guide cable. Good transmission.
 - *Objective Lens & Focussing* – Good optics, few damaged fibres. Focussing functional.
 - *Remote Control Switches* – N/A
 - *Distal End* – Good
 - *Image Quality* – Good image quality



- **Instrument Channel (s)** – N/A
 - **Leak Test** – Pass
 - **Overall Condition** – Reasonable overall condition, small signs of wear.
 - **Dimension:** 3.9 x 300 mm
-

Lot 74 Pentax FNL-10RP3 Fiber Naso-Pharyngo Laryngoscope | SN G116569

- Condition Report:
- **Insertion Tube** – Fair condition, one dent.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good guide cable. Good transmission.
 - **Objective Lens & Focussing** – Good optics, few damaged fibres. Focussing functional.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – N/A
 - **Leak Test** – Pass
 - **Overall Condition** – Reasonable overall condition, small signs of wear consistent with use.
 - **Dimension:** 3.9 x 300 mm
-

Lot 75 Pentax FNL-10RP3 Fiber Naso-Pharyngo Laryngoscope | SN G116618

- Condition Report:
- **Insertion Tube** – Good condition, slight bend in the tube.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good guide cable. Good transmission.
 - **Objective Lens & Focussing** – Good optics, 3 damaged fibres. Focussing functional.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – N/A
 - **Leak Test** – Pass
 - **Overall Condition** – Reasonable overall condition, small signs of wear consistent with use.
 - **Dimension:** 3.9 x 300 mm
-

Lot 76 Pentax FNL-10RP3 Fiber Naso-Pharyngo Laryngoscope | SN G116675

- Condition Report:
- **Insertion Tube** – Good condition, slight bend in the tube.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good guide cable. Good transmission.
 - **Objective Lens & Focussing** – Good optics, few damaged fibres. Focussing functional.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Good image quality



- **Instrument Channel (s)** – N/A
- **Leak Test** – Pass
- **Overall Condition** – Reasonable overall condition, small signs of wear consistent with use.
- **Dimension:** 4 x 300 mm

Lot 77 Pentax FNL-10RP3 Fiber Naso-Pharyngo Laryngoscope | SN G116679

- Condition Report:
- **Insertion Tube** – Good condition, slight bend in the tube.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good guide cable. Good transmission.
 - **Objective Lens & Focussing** – Good optics, no damaged fibres. Focussing functional.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – N/A
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition, small signs of wear consistent with use.
 - **Dimension:** 4 x 300 mm

Lot 78 Olympus CF Type 230L Video Colonoscope | SN 2700953

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – Good condition and light transmission
 - **Objective Lens & Focussing** – Good optics.
 - **Remote Control Switches** – Functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good physical and working condition.
 - **Dimension:** 12 x 1600 mm

Lot 79 Olympus GIF XQ230 Video Gastroscope | SN 2715728

- Condition Report:
- **Insertion Tube** – Good condition
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – Good condition and light transmission
 - **Objective Lens & Focussing** – Good optics.
 - **Remote Control Switches** – Functional
 - **Distal End** – Good condition
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good physical and working condition.



- **Dimension:** 10 x 1000 mm

Lot 80 Pentax FNL-10RP3 Fiber Naso-Pharyngo Laryngoscope | SN G116676

- Condition Report:
- **Insertion Tube** – Fair condition, one dent and a slight bend in the tube.
 - **Bending mechanism & Angulation Control** – Good movement.
 - **Light Guide Cable & Light Transmission** – Good guide cable. Good transmission.
 - **Objective Lens & Focussing** – Good optics, No damaged fibres. Focussing functional.
 - **Remote Control Switches** – N/A
 - **Distal End** – Good
 - **Image Quality** – Good image quality
 - **Instrument Channel (s)** – N/A
 - **Leak Test** – Fail
 - **Overall Condition** – Reasonable overall condition, small signs of wear consistent with use.
 - **Dimension:** 4 x 300 mm

Lot 81 Olympus GIF-HQ290 Video Gastroscope | SN 2513236 | DOM 2015

- Condition Report:
- *Insertion tube – Very good condition*
 - *Bending mechanism & Angulation control – Good movements & locks*
 - *Light guide cable & Light transmission – Good light channels*
 - *Objective lens and focusing – Good optics*
 - *Remote control switches – Fully functional*
 - *Distal end – Very good condition*
 - *Image Quality – Very good image quality*
 - *Working Channel (s) – Clear*
 - *Leak Test – Passed*
 - *Over all condition – Very good overall condition*

Lot 82 Olympus GIF-HQ290 Lucera Gastroscope | SN 2513200 | AN 219 | DOM 2015

- Condition Report:
- *Insertion tube – Very good condition*
 - *Bending mechanism & Angulation control – Good movements & locks*
 - *Light guide cable & Light transmission – Good light channels*
 - *Objective lens and focusing – Good optics*
 - *Remote control switches – Fully functional*
 - *Distal end – Very good condition*
 - *Image Quality – Very good image quality*
 - *Working Channel (s) – Clear*
 - *Leak Test – Passed*
 - *Over all condition – Very good overall condition*

Lot 83 Olympus GIF-HQ290 Lucera Gastroscope | SN 2513201 | AN 218 | DOM 2015

- Condition Report:
- *Insertion tube – Very good condition*
 - *Bending mechanism & Angulation control – Good movements & locks*
 - *Light guide cable & Light transmission – Good light channels*
 - *Objective lens and focusing – Good optics*



- *Remote control switches – Fully functional*
- *Distal end – Very good condition*
- *Image Quality – Very good image quality*
- *Working Channel (s) – Clear*
- *Leak Test – Passed*
- *Over all condition – Very good overall condition*

Lot 84 Olympus GIF-HQ290 Lucera Gastroscope | SN 2513199 | AN 217 | DOM 2015

- Condition Report:**
- *Insertion tube – Very good condition*
 - *Bending mechanism & Angulation control – Good movements & locks*
 - *Light guide cable & Light transmission – Good light channels*
 - *Objective lens and focusing – Good optics*
 - *Remote control switches – Fully functional*
 - *Distal end – Very good condition*
 - *Image Quality – Very good image quality*
 - *Working Channel (s) – Clear*
 - *Leak Test – Passed*
 - *Over all condition – Very good overall condition*

Lot 85 Olympus ESG 400 Diathermy with Footswitches | DOM 03/2014 | SN

Condition Report: The olympus ESG 400 diathermy powers up and completes start up procedures successfully. The touch screen and capacitive buttons are both operational. The return plate indicator / alarm is also functional. Both monopolar and bipolar modes are selectable - basic function checks were carried out on both modes and the output power readings from all configurations corresponded to the set values. Universal output was not tested. Overall the unit is in good physical condition. All three foot switches were fully functional and in good physical condition with some small wear consistent with use.

Lot 115 Olympus CLL-V1 Light Source | SN 13338W000275 | with Light Lead

Condition Report: The CLL-V1 light source powered up as expected. Light was produced with the brightness fully adjustable. The supplied fibre optic cable was in good physical condition. The light source was also in good physical condition.

Lot 119 Ethicon Endo Surgery G11 Generator (No Foot Switch) | DOM 2011 | SN

Serial No: 1111127557

Manufactured: 2011

Accessories: Harmonic device connector
Operator's Manual

Software: Version 2016-1.1

Condition Report: The unit power up and completed the start up initialisation successfully. The touch screen come on and warming of instruments not connected. The setup menu is accessible. Therefore no further tests were possible without instruments. Footswitch is



not included and unit is in fairly good physical condition. Generator run time:
1404:54:01.

Lot 120 Ethicon Endo Surgery G11 Generator (No Foot Switch) | DOM 2011 | SN

Serial No: 1111131741

Manufactured: 2011

Accessories: Harmonic and Enseal device connectors
Operator's Manual

Software: Version 2016-1.1

Condition Report: The unit power up and completed the start up initialisation successfully. The touch screen come on and warming of instruments not connected. The setup menu is accessible. Therefore no further tests were possible without instruments. Footswitch is not included and unit is in fairly good physical condition. Generator run time:
1449:43:16.

Lot 121 Karl Storz Endoskope Tele Pak Pal

Serial No: DB3361-B

Condition Report: Unit power up with LCD and key pad working. A compatible camera head was used to test the system but image failed to display. The light source's xenon lamp is working fine. Unit is in fair physical condition but not fully functional.

Lot 128 GE Logiq E Ultrasound with 3 x Transducers, Power Supply and Case | DOM

Serial No: 114140WX7

Manufactured: 03 2009

Accessories: GE Convex transducer 4C-RS, S/N: 110713WX5 (01/2009)
GE Linear Array transducer 12L-RS, S/N: 30840YP3 (12/2008)
GE TV transducer E8C-RS, S/N: 211835WK4 (11/2011)

Condition Report: The Logiq e power up on mains but failed to boot up; the hard drive is missing. Battery is not working. Unit is in good physical condition with missing HDD thus, not tested.

Lot 129 Olympus BX45 Benchtop Microscope, 2 x Eyepieces, and 5 x Objectives

Serial No: 1G05739

Accessories: Eye pieces WL10x/22 set
Objectives: Plan 10x/0.25, NPL Fuotar 40/0.70, Plan 100x/1.25, SPlan 20 & MP 40Ph.
D.M

Condition Report: The light source's halogen lamp and brightness control are working. Fair optical system but the lens needs cleaning. Objective lenses are in fair condition. Stage adjustment, coarse and fine focus are working fine. Fair overall condition.

Lot 147 Olympus CV-180 Video Processor | SN 7981916 | AN 4957

Condition Report: The video processor was tested with a compatible scope and display. The unit powered up as expected and produced a clear image on the monitor. All functional buttons on the unit are operational. Overall this unit is in good condition.

Lot 150 Martin ME80 Diathermy (No Foot Switch)



Condition Report: The ME80 diathermy powers up and completes start up procedures successfully. The soft key buttons and power dials are operational. The return plate indicator is also functional. Monopolar and bipolar modes are selectable - basic function checks were carried out on monopolar modes only due to lack of compatible bipolar hand pieces. The monopolar output power readings from all configurations corresponded to the set values. Overall the unit is in good physical condition. There are no foot switches included in this lot, functionality was tested using hand switches.

Lot 151 Martin ME80 Diathermy (No Foot Switch)

Condition Report: The ME80 diathermy powers up and completes start up procedures successfully. The soft key buttons and power dials are operational. The return plate indicator is also functional. Monopolar and bipolar modes are selectable - basic function checks were carried out on monopolar modes only due to lack of compatible bipolar hand pieces. The monopolar output power readings from all configurations corresponded to the set values. Overall the unit is in good physical condition, other than one missing rubber foot. There are no foot switches included in this lot, functionality was tested using hand switches.

Lot 152 Laserscope Aura Star Pulse Laser with Key (No Foot Switch) | SN 0790 | DOM

Serial No: 0790

Manufactured: 08 1999

Accessories: Key

1 x Safety goggle

User Manual

Condition Report: Unit power up and during warming "Problem 79" is displayed. Not further tests were possible. Lot is in fair physical condition.

Lot 174 Smith & Nephew HD1200 Camera Head with Coupler

Condition Report: The camera head was tested with a compatible video processor, the system produced very clear images and the camera head buttons, focus control and white balance setting were all functional at the time of test. The coupler (Ref 72200315) is included. Overall the camera head is in reasonable physical condition with minor signs of wear.

Lot 175 Smith & Nephew HD1200 Camera Head with Coupler

Condition Report: The camera head was tested with a compatible video processor, the system produced very clear images and the camera head buttons, focus control and white balance setting were all functional at the time of test. The coupler (Ref 72200315) is included. Overall the camera head is in reasonable physical condition with minor signs of wear

Lot 176 Smith & Nephew HD1200 Camera Head with Coupler



Condition Report: The camera head was tested with a compatible video processor, the system produced clear images and the camera head buttons, focus control and white balance setting were all functional at the time of test. The coupler (Ref 72201635) is included. Overall the camera head is in reasonable physical condition with minor signs of wear.

Lot 183 Toshiba PVT-674BT Transducer

Condition Report: The PVT-674BT transducer is in good condition with the pins and locking mechanism in working order. The probe lens is intact (with some slight wear) and cable in reasonable condition with some discolouration. The transducer was tested on a Toshiba Aplio 500, where an air scan showed no signs of crystal element damage. SN: A4582002.

Lot 192 Storz Tricam Camera Head | AN 4831

Condition Report: The Tricam camera head is in fair physical condition not tested (compatible processor was not available to check the image quality).

Lot 193 Storz Tricam 20221030 Camera Head | AN 4832

Serial No: BG602476-H

Condition Report: Tricam 20221030 PAL camera head is in fair physical condition not tested (compatible processor id not available to check the image quality).

Lot 199 Arthrex AR-3210-0001 Synergy HD3 Camera Head | SN AA2149 | Arthrex AR-3360

Condition Report: The camera head, rigid scope and fibre optic cable are all in good working order. Tested with a compatible video processor, the system produced clear images and the white balance setting, camera head buttons and focus control were all in good working order. Overall the items are in reasonable physical condition with minor signs of wear.

Lot 200 Arthrex AR-3210-0001 Synergy HD3 Camera Head | SN AA1581 | Arthrex AR-3360

Condition Report: The camera head, rigid scope and fibre optic cable are all in good working order. Tested with a compatible video processor, the system produced clear images and the white balance setting, camera head buttons and focus control were all in good working order. Overall the items are in reasonable physical condition with minor signs of wear.

Lot 201 Arthrex AR-3210-0001 Synergy HD3 Camera Head | SN AA3514 | Arthrex AR-3360

Condition Report: The camera head, rigid scope and fibre optic cable are all in good working order. Tested with a compatible video processor, the system produced clear images and the white balance setting, camera head buttons and focus control were all in good working order. The coupler locking mechanism on the camera head is stiff. Overall the items are in reasonable physical condition with minor signs of wear.



Lot 252 Olympus CV- 260 Video Processor with MAJ-1154 Pigtail Connector | AN 4957 |

Condition Report: Both the light source and video processor powered up as expected. The video processor was attached to a monitor and tested with an Olympus scope, a good image was displayed and all image settings and white balance were working as expected. The light source was fully functional, however lamp life was low. Brightness adjustments and light focus were also functional. Both the video processor and light source were in good physical condition with few signs of wear. Pigtail connector and keyboard were functional and in good physical condition. Overall this lot is in good condition.

Lot 280 Eschmann E10 Diathermy (No Foot Switch) | DOM 01/2018 | SN 123189

Condition Report: The Eschmann E10 diathermy powers up and completes start up procedures successfully. The numerical displays and soft key buttons are operational. The return plate indicator is also functional. Both monopolar and bipolar modes are selectable - basic function checks were carried out on both modes and the output power readings from all configurations corresponded to the set values. Overall the unit is in good physical condition.

Lot 290 Karl Storz Stack Trolley with 2 x Monitors, Storz Electronic Endoflator, Storz

Condition Report: .

Lot 299 Episcan I-100 (No HDD) | SN 016 | DOM 08/2000

Condition Report: .

Lot 315 Heine Professional L MD1000 F.O. Head Lamp

Condition Report: Size adjustments were functional. Fibre optic cable was in working order and the head lamp lens focussed light as expected. The unit is in good physical condition.

Lot 320 Draeger Oxylog 3000 Ventilator (Small Crack on Screen) | SN SRSK-0059 | DOM

Condition Report: Unit could not be function tested due to lack of charger and battery. Unit is in fair physical condition.

Lot 321 Parapac 2000D Ventilator | SN 04/08/371

Condition Report: The ParaPAC 200D is missing gas and patient circuit connectors. Unable to test this unit. Average physical condition.

Lot 322 Parapac 2D Ventilator | SN 01/11/517

Condition Report: The ParaPAC 2D is missing gas and patient circuit connectors. Unable to test this unit. The plastic casing has several crack on it. Poor physical condition.

Lot 326 Clement Clark International 904 Portable Slit Lamp in Case



Condition Report: The power supply powers up and the intensity setting for the lamp is working. The light beam, pattern selector and filters are functional. The unit was tested with a focus rod; good optics were observed. Eye pieces (10x) set included. The energy pack was depleted at the time of testing. Unit is in good physical condition with some discolouration on the power supply.

DOM:2004

SN: PC 0313

Lot 332 Haag Streit 900 Slit Lamp | 506182

Condition Report: The slit lamp is without a table or power supply so could not be fully tested. The optical set up however is in good condition with two 10x eyepieces and 1x and 1.6x magnification.

Lot 333 Haag Streit 900 Slit Lamp | 500184

Condition Report: The slit lamp is without a table or power supply so could not be fully tested. The optical set up however is in good condition with two 10x eyepieces and 1x and 1.6x magnification.

Lot 334 Haag Streit 900 Slit Lamp | 500196

Condition Report: The slit lamp is without a table or power supply so could not be fully tested. The optical set up however is in good condition with two 10x eyepieces and 1x and 1.6x magnification.

Lot 355 Penlon Prima SP Anaesthetic Machine | SN SP0204-26 | AN 48837

Serial No: SPO204 21

Accessories: Air, O2 & N2O Hoses
AGSS hose and receiver
Central Vac with regulator

Condition Report: The anaesthetic machine power up with cat eye indicator and pneumatic system are working. Flow meter assembly with anti-hypoxic device, pressure gauges, Basel flow and O2 flush are working fine. The O2 monitor power with displays and key pad working. The O2 sensor is included but failed to calibrate. Battery is low as well. The low supply gas alarm is working as well. Overall the unit is in good physical condition.

Lot 356 Penlon Prima SP Anaesthetic Machine | SN SP0204-24 | AN 48839

Serial No: SPO 204 24

Accessories: Air, O2 & N2O Hoses
AGSS hose and receiver
Central Vac with regulator

Condition Report: The anaesthetic machine power up with cat eye indicator and pneumatic system are working. Flow meter assembly with anti-hypoxic device, pressure gauges, Basel flow and O2 flush are working fine. The O2 monitor is not coming on and the O2 sensor is missing. The low supply gas alarm is working as well. Overall the unit is in good physical condition.



Lot 357 Mortara ELI 280 ECG Machine on Trolley (No Leads)

Condition Report: The ELI 280 ECG machine powered up and completed start up procedure successfully. The touch screen was fully operational. The unit was tested with an ECG simulator and a spare set of ECG leads where good waveforms were recorded and displayed. Printer was operational and produced good quality prints. Back up battery was functional at the time of testing. Overall the unit was in good physical condition, with only small signs of wear consistent with use. The trolley was in a reasonable condition, with areas of wear.
SN:113080153982
Software: V2.2.2.3

Lot 358 Kowa Nonmyd WX 3D Retinal Camera on Table with Stills Camera

Serial No: 31863800112

Manufactured: 2015

Accessories: Electric Table

Software: Ver. 0 1021

Condition Report: System power up and the WX3D's LCD and soft key are working. Function menu is accessible. The camera is displaying image on the LCD. The unit is without a PC therefore no test or measurements were possible. Motorised chin rest and fixation lamp are working fine. The Nikon D70 digital camera is without battery pack or power adapter or SD card, not possible to test. However, both items are in good physical condition. The motorised table is working but it is missing one caster.

Lot 359 Datex Ohmeda Aestive 5 Anaesthetic Machine | SN AMRE01623 | DOM 2001

Condition Report: The Aestiva/5 powers up and the Smart Vent (SW: 3.5) completes the system self test successfully. Pressure gauges, flow meters and O2 flush are working. Anti-hypoxic feature and basal flow are in good working order. The LCD, key pad and rotary selector knob of the Smart Vent are fully functional. System was tested with medical air and test lung. Good ventilation cycles were delivered with the set tidal volume and breath frequency (BPM) corresponding to the measured minute volume. All ventilator modes (volume and pressure control) are operational. Flow sensors, bellows and absorber are in good working condition. O2 sensor failed calibration. Backup battery was not functional. Lot is in good physical condition, with minor signs of wear.

Lot 360 Storz Stack Trolley with Wideview HD Monitor, Storz Aida Control and Sony

Condition Report: .

Lot 365 Siemens Accuson S2000 Ultrasound (No Transducers) | SN 205906 | DOM 03/2012

Serial No: 205906

Manufactured: 03 2012

Condition Report: The ultrasound powered up as expected. Keyboard was faulty, control panel was missing two dials and the control wheel was in working order. Unit could not be fully tested due to lack of compatible probes. Height and control board adjustments were in working order. Overall the unit is in fair physical condition with signs of wear across the



control panel.

Lot 366 Kowa Nonmyd 3D Retinal Camera on Table with Stills Camera

Serial No: 31815120062

Manufactured: 2014

Accessories: Electric table
Brother HL-5450DN printer

Software: Ver. 0.1023

Condition Report: System power up and the WX3D's LCD and soft key are working. Function menu is accessible. The camera is displaying image on the LCD. The unit is without a PC therefore no test or measurements were possible. Motorised chin rest and fixation lamp are working fine. The Nikon D200 digital camera is without battery pack or power adapter or SD card, not possible to test. However, both items are in good physical condition. The motorised table is in good working order.

Lot 368 Canon Full Auto Ref R-Fio Refractometer on Table

Condition Report: Unit power up with CRT, soft keys and trackball working fine. The Camera head motorised adjustments are functional and so is the chin rest. The camera is showing images but system was not fully tested. The table height adjustment was faulty the unit only moves downwards (due to a damaged switch). System is in good physical condition.

Lot 371 Ethicon Endo Surgery G11 Generator on Trolley | DOM 2011 | SN 1111136767

Serial No: 1111136767

Manufactured: 09 2011

Accessories: Harmonic Device connector
Trolley

Software: Version 2016-1

Condition Report: The unit power up and completed the start up initialisation successfully. The touch screen come on and warming of instruments not connected. The setup menu is accessible. Therefore no further tests were possible without instruments. Footswitch is not included and unit is in fairly good physical condition. Generator run time: 1434:58:20.

Lot 372 Ethicon Endo Surgery G11 Generator on Trolley | DOM 2011 | SN 1111138780

Serial No: 1111136780

Manufactured: 09 2011

Accessories: Harmonic Device connector
Trolley

Software: Version 2016-1.1

Condition Report: The unit power up and completed the start up initialisation successfully. The touch screen come on and warming of instruments not connected. The setup menu is accessible. Therefore no further tests were possible without instruments. Footswitch is not included and unit is in fairly good physical condition. Generator run time:



1461:54:26.

Lot 374 Schiller AT-102 ECG Machine with Leads on Trolley

Condition Report: Unit powers up with functional screen.

Lot 375 Schaerer Operating Table with Remote and Accessories Rack

Condition Report: The operating table powered up with corded hand control display and key pad working. The battery was used during testing. All motorised positioning and adjustments were functional. Emergency key pad is working ok. The cushions are in fair physical condition with minor wear and tear. Motorised floor lock and casters were functional. Lot is in reasonable physical condition with minor signs of wear consistent with use. The accessories rack and accessories are in good physical condition however remain untested.

Lot 376 DP Medical Stack Trolley with Monitor, DVC 750 Processor and Canon Selphy

Condition Report: .

Lot 377 Valleylab Cusa Excel Surgical Aspirator with Foot Switch | DOM 09/2007 | SN

Serial No: U712908S

Manufactured: 09 2007

Associated Equipment: Cusa EXcel Foot Switch

Serial number: 689087

Manufactured: 02-2007

Condition Report: This system powers-up, with LEDs and audible signals working as expected, but remains untested due to a lack of compatible accessories. The footswitch is in good physical condition. The system is in good physical condition, with wheel caster-locks in good working order.

Lot 378 Valleylab Cusa Excel Surgical Aspirator with Foot Switch | DOM 03/2003 | SN U3C

Serial No: U3C 1478S

Manufactured: 03 2003

Accessories: Foot Switch

Condition Report: The unit powers up and completes the initial system self test accordingly. The footswitch is detectable and appears to be functional. No further checks could be carried out due to lack of accessories/attachments. The unit is in reasonable physical condition with minor signs of wear and scratch marks to the paintwork.

Lot 379 Conmed System 7550 Electrodergical Generator with Monopolar Foot Switch |

Serial No: 13FGV003

Manufactured: 2012

Accessories: Monopolar Foot Switch

Condition Report: The unit powers up with alphanumerical displays, key pads and indicators in good



working order. RF power and modes selector are fully functional. System was tested with electrosurgical analyser in both monopolar and bipolar modes. All set RF output powers were well within the set limits. The return patient plate monitors and selection of split and single plates are working fine. The footswitch and handpiece control are fully functional. The Argon Beam Coagulator display and function key are working but this mode was not fully tested. Argon gas cylinder is not included. Both units are in fair physical condition with minor scuffs and some rusty patches on the base shelves, consistent with use.

Lot 380 Getinge Endoscope Reprocessor ED-Flow AER | DOM 2013 | SN 3H020207

Serial No: 3H020207

Manufactured: 2013

Condition Report: System was in good working order before disconnection and removal from the hospital.

Lot 381 Getinge Endoscope Reprocessor ED-Flow AER | DOM 2014 | SN 4H010285

Serial No: 4H010285

Manufactured: 2014

Condition Report: The unit is in reasonable physical condition but has not been tested. The emergency stop release key, instrument baskets and drain trays are not included.

Lot 382 Getinge Endoscope Reprocessor ED-Flow AER | DOM 2014 | SN 4H010284

Serial No: 4H010284

Manufactured: 2014

Condition Report: The unit is in reasonable physical condition but has not been tested. The emergency stop release key, instrument baskets and drain trays are not included.

Lot 383 Getinge Endoscope Reprocessor ED-Flow AER | DOM 2013 | SN 3H020208

Serial No: 3H030208

Manufactured: 2013

Condition Report: System was in good working order before disconnection and removal from the hospital

Lot 384 Conmed System 7550 Electrosurgical Generator with Monopolar Foot Switch and

Serial No: 12MGV013

Manufactured: 2012

Accessories: Monopolar Foot Switch
Bipolar foot switch

Condition Report: The unit powers up with alphanumeric displays, key pads and indicators in good working order. RF power and modes selector are fully functional. System was tested with electrosurgical analyser in both monopolar and bipolar modes. All set RF output powers were well within the set limits. The return patient plate monitors and selection of



split and single plates are working fine. The footswitch and handpiece control are fully functional. The Argon Beam Coagulator display and function key are working but this mode was not fully tested. Argon gas cylinder is not included. Both units are in fair physical condition with minor scuffs and some rusty patches on the base shelves, consistent with use.

Lot 385 Imotech Medical Sure Scope 3Di Scope Positioning with 3 x Endoscopic

Accessories: 3 x Endoscopic Catheters

Software: 2.0.0

Condition Report: This scope positioning system powered up with the touchscreen in working order. The unit was tested with one of the endoscopic catheters. Clear and accurate 3D images were produced. The marker and probe interface were fully operational. Overall this unit is in good physical condition.

Lot 386 Imotech Medical Sure Scope 3Di Scope Positioning with 3 x Endoscopic

Serial No: 201003026

Accessories: 3 x Endoscopic Catheters

Software: 2.0.0

Condition Report: This scope positioning system powered up with the touchscreen in working order. The marker and probe interface were not detected by the system despite being in working order (tested on another unit). The unit could not be fully tested due to this issue. The unit is in good physical condition.

Lot 388 Viasys Advantech Computer/Monitor with Nicolet One Module on Stand | 127140

Condition Report: .

Lot 394 Valleylab Force EZ C Diathermy with Foot Pedals on Trolley

Condition Report: The Force FX diathermy powers up and completes start up procedures successfully. The numerical displays, soft key buttons and power dials were operational. The return plate indicator/alarm is also functional. Both monopolar and bipolar modes are selectable - basic function checks were carried out on both modes and the output power readings from all configurations corresponded to the set values. Overall the unit is in good working order and fair physical condition, with signs of wear consistent with use. Monopolar and bipolar foot switches were both in working order. The trolley is in fair physical condition.

Lot 397 Aksys Dialysis Machine | D100215

Condition Report: .

Lot 402 Cynosure Smartcool Cryo 5 Cryo Unit

Condition Report: The cryo unit powers up successfully with all functional buttons and numerical displays in working order. The therapy tubing is damaged, the unit was tested with a spare. Cold air was produced as expected at all different fan speeds. Overall this unit is in good



condition with few signs of wear and working as expected.

Lot 403 Cynosure Smartcool Cryo 5 Cryo Unit

Condition Report: The cryo unit powers up successfully with all functional buttons and numerical displays in working order. Cold air was produced as expected at all different fan speeds. Overall this unit is in good condition with few signs of wear and working as expected.

Lot 404 Haag Streit Bern 900 Slit Lamp on Table

Condition Report: The slit lamp power supply, lamp and intensity control are in good working order. The optical fair optical system and good magnification (Steps: 1 & 1.6). System was tested with a focus rod. Light beam patterns and filter are working fine. Eye pieces included, : mag 10x. The table mechanical height adjustment is working. System is in fair physical condition with some scratches.

Lot 405 Philips IU22 Ultrasound (No Probes) | DOM 2007

Serial No: 02R710

Manufactured: 02 2007

Accessories: Sony video graphic printer UP-897

Software: 6.0.0845

Condition Report: The unit power up and completed the system initialisation successfully. The keyboard, control console and LCDs are working fine. There is no transducer with this lot therefore system was not fully tested. Lot is in fair physical condition with small crack on the control console plastic frame.
E type cart

Lot 409 Welch Allyn GS900 Mobile Examination Lamp

Condition Report: Examination powers up and works as expected. Intensity controls are working. The unit is in fair condition with some signs of wear and case cracks consistent with use.

Lot 410 Carl Zeiss 150-FC Colposcope

Condition Report: The unit powers on and light output and brightness adjustments are working as expected. Arm mechanic adjustments are functional and optics stays in the required position. All optics are clear and mechanical focus and zoom adjustments are working fine. Overall the unit is in fair condition with some signs of wear consistent with use.
f = 300
Eyepieces = 10x set and One 12.5x
Zoom levels = 0,4 - 0,6 - 1,0 - 1,6 and 2,5.

Lot 421 Giraffe Omnibed Incubator

Serial No: HDGK52112

Manufactured: 10 2006

Accessories: O2 hose



Baby mattress

Condition Report: The OmniBed power up and completed the system self-tests successfully. The LCD, numerical displays, rotary selector knob and key pad are working fine. Function menus are accessible. The canopy motorised control and cot motorised height adjustments are functional. Unit was tested in the air temperature mode; set temperatures was maintained accordingly. Skin temperature mode is available but was not tested. The oxygen sensor need calibration. Humidifier monitor was not fully tested, the water container is included. Over head radiant heater is working as well. Baby mattress is not included. Lot is in fair physical condition. Examination lamp is working.

Lot 422 ECG Recorder with Leads on Trolley | DOM 2003

Condition Report:

Lot 424 Mortara ELI 350 ECG Machine with Leads on Trolley | 29536

Condition Report: Burning smell on power up.

Lot 425 GE MAC 5500 HD ECG Recorder on Trolley (No Leads) | AN 010777

Condition Report: Screen damaged, some missing pixels.

Lot 427 Ohmeda Giraffe Omnibed Incubator

Serial No: HDGK51064

Manufactured: 03 2006

Accessories: O2 hose

Baby mattress

Condition Report: The OmniBed power up and completed the system self-tests successfully. The LCD, numerical displays, rotary selector knob and key pad are working fine. Function menus are accessible. The canopy motorised control and cot motorised height adjustments are functional. Unit was tested in the air temperature mode; set temperatures was maintained accordingly. Skin temperature mode is available but was not tested. The oxygen sensor need calibration. Humidifier monitor was not fully tested, the water container is included. Over head radiant heater is working as well. Baby mattress is not included. Lot is in fair physical condition.

Lot 428 GE Datex Ohmeda Aisys Anaesthetic Machine Machine with Monitor (Incomplete)

Condition Report: The Aisys anaesthetic machine powers up and completes the initial system self test successfully. LCD screen, rotary control knob and key pad are in good working order. Digital pressure gauges and flowmeters are working accordingly. Available ventilation modes include VCV, PCV, SIMV/PSV, PSV Pro, SIMV-PC & PCV-VG. Flow sensors, O2 sensor, bellows and CO2 absorber canister are in place. The system was tested with medical air and test lung, good ventilation cycles were delivered and the measured readings corresponded to the set values. The backup battery also found to be working at the time of test. Overall the unit is in reasonable physical condition with general signs of wear and scratch marks on the worktop and around the ventilator control screen. The unit comes with medical gas hoses, O2, Air & N2O.



Lot 429 GE Mac 5500 ECG Machine with Leads on Trolley | SCD093966 75 PA

Condition Report:

Lot 430 GE Mac 5500 ECG Machine with Leads on Trolley | SCD10299389 PA

Condition Report:

Lot 471 Olympus URF P5 Fiber Ureteroscope | SN W040858

- Condition Report:
- **Insertion Tube** – Fair condition, with one dent.
 - **Bending mechanism & Angulation Control** – Good movements and lock
 - **Light Guide Cable & Light Transmission** – Good transmission, no light guide cable.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – N/A
 - **Distal End** – Good condition
 - **Image Quality** – Fair, 10+ damaged fibres.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Reasonable overall condition with damaged fibres and dented insertion tube.
 - **Dimension:** 3 x 670 mm
-

Lot 472 Olympus GIF-Q260 Video Gastroscope | SN 2432678 | DOM 2014

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Reasonable movements and good locks
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 10.1 x 1000 mm
-

Lot 473 Olympus GIF-Q260 Video Gastroscope | SN 2421642 | DOM 2014

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Reasonable movements and good locks
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics



- **Remote Control Switches** – Good
- **Distal End** – Good condition
- **Image Quality** – Good quality.
- **Instrument Channel (s)** – Clear
- **Leak Test** – Passed
- **Overall Condition** – Good overall condition.
- **Dimension:** 10.2 x 1000 mm

Lot 474 Olympus GIF-Q260 Video Gastroscope | SN 2533004 | DOM 2015

- Condition Report:
- **Insertion Tube** – Fair condition, one dent.
 - **Bending mechanism & Angulation Control** – Reasonable movements and good locks
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Fair condition, one damaged light lens.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition, with small signs of wear.
 - **Dimension:** 10.1 x 1000 mm

Lot 475 Olympus GIF-XQ260 Video Gastroscope | SN 2723488 | DOM 2007

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements and locks
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 9.9 x 1000 mm

Lot 476 Olympus CF-260DL Video Colonoscope | SN 2510339 | DOM 2015

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements and locks
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear



- **Leak Test** – Pass
- **Overall Condition** – Good overall condition.
- **Dimension:** 13 x 1600 mm

Lot 477 Olympus GIF-Q260 Video Gastroscope | SN 2421574 | DOM 2014

- Condition Report:
- **Insertion Tube** – Fair condition, some kinks.
 - **Bending mechanism & Angulation Control** – Reasonable movements and good locks
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition, with small signs of wear.
 - **Dimension:** 10.6 x 1000 mm

Lot 478 Olympus PCF-Q260AL Video Colonoscope | SN 2410115 | DOM 2014

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements and locks
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Pass
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 12.2 x 1600 mm

Lot 479 Olympus CF-Q260DL Video Colonoscope | SN 2510188 | DOM 2015

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Poor movements, down angulation is not functional.
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Fair overall condition, with damaged bending mechanism.
 - **Dimension:** 13.9 x 1600 mm



Lot 480 Olympus GIF-Q260 Video Gastroscope | SN 2533000 | EST DOM 2015

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements and locks.
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 10.2 x 1000 mm
-

Lot 481 Olympus GIF-Q260 Video Gastroscope | SN 2543694 | EST DOM 2015

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Reasonable movements, good locks.
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 10.4 x 1000 mm
-

Lot 482 Olympus GIF-XQ260 Video Gastroscope | SN 2411047 | EST DOM 2014

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Reasonable movements, good locks.
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 10.2 x 1000 mm
-

Lot 483 Olympus SIF-Q240 Video Enteroscope | SN 2510098 | EST DOM 2005

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Reasonable movements and locks.
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.



- **Objective Lens & Focussing** – Good optics
- **Remote Control Switches** – Good
- **Distal End** – Good condition.
- **Image Quality** – Good quality.
- **Instrument Channel (s)** – Clear
- **Leak Test** – Failed.
- **Overall Condition** – Fair overall condition.
- **Dimension:** 10.1 x 2000 mm

Lot 484 Olympus CF-Q260 Video Colonoscope | SN 2410110 | EST DOM 2005

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements, good locks.
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 12.6 x 1600 mm

Lot 485 Olympus CF-Q260 Video Colonoscope | SN 2510208 | EST DOM 2015

- Condition Report:
- **Insertion Tube** – Good condition, other than some small damage at the control body end.
 - **Bending mechanism & Angulation Control** – Good movements and locks.
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 14 x 1600 mm

Lot 486 Olympus CF-Q260 Video Colonoscope | SN 2510210 | EST DOM 2015

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements and locks.
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.



- **Instrument Channel (s)** – Clear
- **Leak Test** – Passed
- **Overall Condition** – Good overall condition.
- **Dimension:** 12.6 x 1600 mm

Lot 487 Olympus CF-Q260 Video Colonoscope | SN 2510189 | EST DOM 2015

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements and locks.
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 12.6 x 1600 mm

Lot 488 Olympus CF-Q260 Video Colonoscope | SN 2510382 | EST DOM 2015

- Condition Report:
- **Insertion Tube** – Good condition.
 - **Bending mechanism & Angulation Control** – Good movements and locks.
 - **Light Guide Cable & Light Transmission** – Good transmission and condition.
 - **Objective Lens & Focussing** – Good optics
 - **Remote Control Switches** – Good
 - **Distal End** – Good condition.
 - **Image Quality** – Good quality.
 - **Instrument Channel (s)** – Clear
 - **Leak Test** – Passed
 - **Overall Condition** – Good overall condition.
 - **Dimension:** 12.6 x 1600 mm

Lot 500 Zeiss Opmi-1 Operating Microscope

Serial No: 88964

Accessories: Objective lens f=200
Eye piece set 10x/22B

- Condition Report: The light's source's lamp and intensity control are working fine. The optical system is clear with good magnification. Mechanical X-Y adjustment are in good working order. The unit is aged but fully functional.

Lot 509 Olympus OB 300 Colposcope

Serial No: 106033

- Condition Report: The light source's halogen lamp and brightness control are working. The fibre optic guide cable is in fair condition. Fair optical system and magnification. The objective lens is chipped and there are some missing screws for the binocular cover. Objective lens



F=300 and eye piece G20 set.

Lot 511 Panasonic KX-BP535 Electronic Whiteboard

Condition Report: The unit powered up successfully, all board movements were functional and the printer was working as expected. Overall the unit is in reasonable physical condition with wear consistent with use.

Lot 518 Zeiss Opmi-6C Operating Microscope

Serial No: 123027

Condition Report: The light source's halogen lamp and brightness control are working. The fibre optic guide cable is in fair condition. Average optical system and magnification. Objective lens f=300 and eye piece 10x/22B set. Average overall condition.

Lot 519 Zeiss Opmi-MDM Colposcope

Serial No: 184428

Condition Report: The light source's halogen lamp and brightness control are working. The fibre optic guide cable is in fair condition. Good optical system but the magnification adjustment is not working; stuck in one position. Objective lens f=300 and eye piece 10x mag set. Fair physical condition.

Lot 524 Philips Pagewriter 300 Pi ECG Machine with Leads on Trolley

Condition Report: Units powers up succesfully, not fully tested.

Lot 529 Scan Med Multi-Dop T Digital Doppler on Trolley (No Leads)

Condition Report: .

Lot 532 Agfa CR35-X CR Reader | DOM 11/2006

Condition Report: Unit powered up and failed self test, Service 22490 message appears. Unit is in fair physical condition.

Lot 533 Blease Frontline Plus 440 Anaesthetic Machine with Blease 8200S Ventilator

Condition Report: The frontline plus powers up successfully. Pressure gauges, flow meters and O2 flush are working. Anti-hypoxic feature and basal flow are in good working order. The 8200s ventilators keys and rotary selector knobs were fully functional. System was tested with medical air and test lung. Good ventilation cycles were delivered in both adult and paed modes. No patient parameters could be tested due to a lack of sensors. Bellows and absorber are in good working condition. Backup battery was functional at the time of testing. Overall the lot is in reasonable physical condition, with minor signs of wear.

Lot 534 Olympus Stack Trolley with Sony Monitor, Olympus OTV-S7 Processor, CLV-S35

Condition Report: The stack system powered up as expected. All components were in full working order. The camera (cable has been repaired with electrical tape) and video processor



produced clear images with functional buttons on both items working as expected. The light source was operational with 200hrs (approx.) of lamp time remaining. Printer produced good prints and the keyboard and monitor were both in good working and physical order. Overall all items in this lot including the trolley were in good physical condition.

Light source SN: 7312131
Video Processor SN: 7292148
Printer SN: 715004

Lot 535 Storz Stack Trolley with 2 x Monitors, Storz Thermoflater, Sony Colour Video
Serial No: PC Serial 2360132P

Condition Report: .

Lot 537 Karl Storz Stack Trolley with 2 x Monitors, Storz Aida Control, Storz Image 1 Hub

Condition Report: .

Lot 702 Nidek AR-600A Auto Refractometer on Table

Condition Report: Unit powered up with CRT screen, functional buttons, height and horizontal adjustments working as expected. The unit produced an image, but was not fully tested. The height adjustable table is working. Overall this unit is in good physical condition with small signs of wear consistent with use.

Lot 704 Resironics Bipap Vision Ventilator

Condition Report: Unit powered up with LCD and key pad in good working order. The unit completed its self start tests then continuously beeps and illuminates the red service icon. The unit was tested no further. Backup battery is not working and system is in fair physical condition with regions of wear.
SN: 107920

Lot 705 Resironics Bipap Vision Ventilator

Condition Report: Unit powered up with LCD and key pad in good working order (some keys and the screen have some cosmetic damage). The unit completed its self start tests. Function menus are accessible and parameter and alarm settings are functional. The air turbine is working fine. Basic tests were carried out on the system. Mode: S/T & CPAP were both operational. Backup battery is not working and system is in fair physical condition with regions of wear.
SN: 107906

Lot 709 Welch Allyn CP 2000 ECG Machine on Trolley (No Leads)

Condition Report: Display damaged, still functional. Item not fully tested.

Lot 729 1 x Fukida Denshi DS-7680, 1 x Fukida Denshi DS-7100 and 1 x Fukida HS-700

Condition Report: .



Lot 780 Kontron Monitor and Kontron Envoy Processor | 21544

Serial No: ENCPUT1364

Condition Report: .

Lot 791 Eschmann Little Sister SES 2258 Autoclave

Condition Report: The unit powered up successfully, on start up a warning message 'Service required please contact Eschmann' is present. The autoclave was not fully tested. The door locking mechanism is functional. Overall the lot is in good physical condition with all buttons and screen in working order.

Lot 926 Medi Watch Urosonic Scanner with 1 x Probe

Condition Report: .

Lot 951 Cardiac Science Burdick 8500 ECG on Roll Stand

Condition Report:

Lot 952 Mediwatch Ultrasound with HP Scanjet 5590 Printer and Mediwatch 3.5/5.0MHz

Serial No: 04420040

Associated Equipment: HP Scanjet 5590 Scanner

Accessories: Mediwatch 3.5/5.0 MHz Transducer
Serial Number 04385005

Condition Report: The ultrasound unit powers up and completes the initial system self test successfully. Display screen, control panel and trackball are working accordingly. Both system modes (2D and M-Mode) are functional. The transducer is in good working order, the system produced clear images with good resolution and greyscale and the calliper measurement is also functional. The scanner has not been tested due to the mains power adaptor not being included. Overall the ultrasound unit is in satisfactory physical condition.

Lot 978 Blease Frontline Plus 560 Anaesthetic Machine with Blease Series 900 Ventilator

Condition Report: The Blease anaesthetic machine was functioning as expected. All start up tests were completed successfully. Unit was tested with medical air and pipeline pressure gauges, flowmeters & O2 flush were all in working order. The breathing assembly was without any leaks and was in good physical condition. Anti hypoxic and basal flow safety features were functional. The blease oxygen monitor did not power on. The 900 series ventilator was operational with the control wheel and touch screen in working order. The system maintained ventilation cycles as expected with set breath rate and tidal volume corresponding to the resulting minute volume. Ventilation modes included, volume and pressure control modes, both of which were tested and working as expected. There is no O2 sensor included with this lot. The unit is in reasonable physical condition with signs of wear consistent with use. The Spacelabs Ultraview SL Gas Module remains



untested.

Lot 979 Blease Frontline Plus 560 Anaesthetic Machine with Blease Series 900 Ventilator

Condition Report: The Blease anaesthetic machine was functioning as expected. All start up tests were completed successfully. Unit was tested with medical air and pipeline pressure gauges, flowmeters & O2 flush were all in working order. The breathing assembly was without any leaks and was in good physical condition. Anti hypoxic and basal flow safety features were functional. The blease oxygen monitor did not power on. The 900 series ventilator was operational with the control wheel and touch screen in working order. The system maintained ventilation cycles as expected with set breath rate and tidal volume corresponding to the resulting minute volume. Ventilation modes included, volume and pressure control modes, both of which were tested and working as expected. There is no O2 sensor included with this lot. The unit is in reasonable physical condition with signs of wear consistent with use. The Spacelabs Ultraview SL Gas Module remains untested.

Lot 980 Blease Frontline Plus 560 Anaesthetic Machine with Blease Series 900 Ventilator

Condition Report: The Blease anaesthetic machine was functioning as expected. All start up tests were completed successfully. Unit was tested with medical air and pipeline pressure gauges, flowmeters & O2 flush were all in working order. The breathing assembly was without any leaks and was in good physical condition. Anti hypoxic and basal flow safety features were functional. The blease oxygen monitor did not power on. The 900 series ventilator was operational with the control wheel and touch screen in working order. The system maintained ventilation cycles as expected with set breath rate and tidal volume corresponding to the resulting minute volume. Ventilation modes included, volume and pressure control modes, both of which were tested and working as expected. There is no O2 sensor included with this lot. The unit is in reasonable physical condition with signs of wear consistent with use. The Spacelabs Ultraview SL Gas Module remains untested.

Lot 981 Blease Frontline Plus 560 Anaesthetic Machine with Blease Series 900 Ventilator

Condition Report: The Blease anaesthetic machine was functioning as expected. All start up tests were completed successfully. Unit was tested with medical air and pipeline pressure gauges, flowmeters & O2 flush were all in working order. The breathing assembly was without any leaks and was in good physical condition. Anti hypoxic and basal flow safety features were functional. The blease oxygen monitor did not power on. The 900 series ventilator was operational with the control wheel and touch screen in working order. The system maintained ventilation cycles as expected with set breath rate and tidal volume corresponding to the resulting minute volume. Ventilation modes included, volume and pressure control modes, pressure support, SIMVPC + PSV & SIMV-PSV. There is no O2 sensor included with this lot. The unit is in reasonable physical condition with signs of wear consistent with use. The Spacelabs Ultraview SL Gas Module remains untested.



Lot 994 Nikon Eclipse E400 Benchtop Microscope with 2 x Eyepieces and 4 x Objectives

Serial No: 679495

Accessories: 1 x Nikon Objective lens Plan 20x/0.40
1 x Nikon Objective lens Plan 4x/0.10
1 x Nikon Objective lens Plan UW 2x/0.06
1 x Nikon Objective lens Plan 40x/0.65

Condition Report: The light source's halogen lamp and brightness control are working. The halogen bulb back cover is missing. Good optical system and the objective lenses are in good condition. Stage adjustment, coarse and fine focus are working fine. Eye piece CFI 10x/22 set. Good overall condition except for the missing back cover.

Lot 1008 Erbe ICC 80 Diathermy (No Foot Switch)

Condition Report: The Erbe ICC 80 diathermy powers up and completes start up procedures successfully. The numerical displays and soft key buttons are operational. The return plate indicator/alarm is also functional. Both monopolar and bipolar modes are selectable - basic function checks were carried out on both modes and the output power readings from all configurations corresponded to the set values. Overall the unit is in good physical condition.

Lot 1009 Erbe ICC 50 Diathermy (No Foot Switch)

Condition Report: The Erbe ICC 50 diathermy powers up and completes start up procedures successfully. The numerical displays and soft key buttons are operational. The return plate indicator/alarm is also functional. Both monopolar and bipolar modes are selectable - basic function checks were carried out on both modes and the output power readings from all configurations corresponded to the set values. Overall the unit is in good physical condition.

Lot 1010 Erbe ICC 50 Diathermy (No Foot Switch)

Condition Report: The Erbe ICC 50 diathermy powers up and completes start up procedures successfully. The numerical displays and soft key buttons are operational. The return plate indicator/alarm is also functional. Both monopolar and bipolar modes are selectable - basic function checks were carried out on both modes and the output power readings from all configurations corresponded to the set values. Overall the unit is in good physical condition.

Lot 1080 Quest 88 Nalk Assist

Condition Report: Date of manufacture: 04/09/02
Electronic seat belt & controller functional .
Seat belts in good condition.
Overall the unit is in reasonable physical condition with signs of wear expected with age and use.
HB41000-00002



Lot 1092 Philips Pagewriter Trim II ECG Machine

Condition Report:

Lot 1176 GE Mac 1200 ST ECG Machine with Leads on Trolley

Condition Report: Unit powered up on battery with screen and all functional buttons in working order.
Software Version: 6.2

Lot 1178 Stack Trolley with Lemke Monitor, Luxtec Model 9300XSP Light Source, Digital

Condition Report: .

Lot 1471 Zeiss Humphrey 720i Field Analyser (No HDD)

Condition Report: The unit powers up but fails to boot-up due to the hard drive being removed. Display screen, chin rest adjustment and motorised table are working accordingly. The lens holder is in place. Patient response button is not included. The printer appears to be working but has not been fully tested. The printer holding bracket is partially loose. Overall the unit is in reasonable physical condition with minor signs of wear.

Lot 1472 Zeiss Humphrey 750i Field Analyser | 127110

Condition Report: The unit powers up but fails to boot-up due to the hard drive being removed. Display screen, chin rest adjustment and motorised table are working accordingly. The lens holder is in place. Patient response button is also included. The printer appears to be working but has not been fully tested. Overall the unit is in reasonable physical condition with minor signs of wear.

Lot 1473 Zeiss Humphrey 720i Field Analyser (Damaged and No HDD)

Condition Report: The unit powers up but fails to boot-up due to the hard drive being removed. Display screen, chin rest adjustment and motorised table are working accordingly. The lens holder is in place. Patient response button is not included. The printer appears to be working but has not been fully tested. Overall the unit is in reasonable physical condition with minor signs of wear. The plastic cover for the chin rest is missing.

Lot 1585 2 x HP PC Towers

Condition Report: .

Lot 1627 GE Processor Module

Serial No: JA106385731GA

Condition Report: .



Lot 1723 AGFA CR35 CR Reader with Cassettes and Monitor

Condition Report: .

Lot 1724 Medgraphics Platinum Elite DX Body | DOM 2008 | SN 227000035 | with Mobile

Serial No: 227000035

Manufactured: 06 2008

Accessories: Mobile Work Station
Desktop Computer
17 Inch Monitor
Deskjet D4200 Printer
PowerVar UPS

Software: v 7.1.0.32

Condition Report: The computer power up and Windows Professional XP start up completed. Breeze Suite software is loaded on the system and is accessible. Function menus are working, patient registration, reporting and review are working fine. The body box power up as well but there are no gas connectors, regulators, umbilical or tubing & accessories. Therefore, it was not possible to fully test the system. Body box is in fair physical condition with scuffs on the breathing assembly. The three-litre calibrated syringe and printer is missing.

Lot 1768 Synchromed 8820 Programmer and Epson Action Note 4000 (Damaged) |

Serial No: NCP001392P

Condition Report: .

Lot 1822 Shandon Cryotome E Cryostat | SN CS1005F9704

Serial No: CS1005F9704

Condition Report: The Cryostat system powers up accordingly. Display panel, function keys, lamp, cutting mechanism and emergency stop are in good working order. No further checks carried out. Overall the unit is in satisfactory physical condition.

Lot 1916 HP Compaq PC Tower | D6459

Condition Report: .

Lot 1928 IDEXX VetLab Station Monitor and Dell Optiplex 3020 Computer | DOM 08/2014

Condition Report: .

Lot 1937 Dell Optiflex 745 Desktop and Dell Monitor | DOM 12/2007

Condition Report: .

Lot 1954 2 x Parc Scientific A/S Automatic Cutting Device ACD-4 MK3



Condition Report: .

Lot 1981 Adec Excellence Dental Suite with Examination Light, Spitoon and Instrument

Serial No: E911048

Accessories: Examination Light
Spitoon
Instrument Station

Condition Report: Sold as seen, dismantled and in our storage facility

Lot 1982 Adec Excellence Dental Chair

Condition Report: Sold as seen, dismantled and in our storage facility
